


UCAMA Construction Report #7

Because of the number of inquiries we have received regarding the progress of our new museum facility on Jasper Avenue, UCAMA has decided to prepare month end construction reports. These reports will be sent out to our friends and supporters until Phase 1 is complete.

The main floor of our new home has been poured and is in the process of curing. This is a major milestone in the construction of the building as we enter the more difficult winter construction season. We are now out of the ground! This month's construction report features photographs for those who were not fortunate enough to see the actual pouring.



Few people have the opportunity to see the "forest" of temporary columns in the basement that are used to support the forms for the first floor as it is being poured.

The grid of steel rebar used to reinforce the concrete floor provides a wonderful visual portrayal of srength of our future home.



But it is not steel alone or machinery that creates a home. The hands of skilled workers can be seen everywhere.





Stay tuned for further updates next month.

Photographs this month are courtesy of Horace Oliver.